From: borawford 3 slm. ga gov Subject. Hobby boilers

Date: October 21, 2014 at 7:41 AM

To: genejoanlocomotives@windstream.net the LFogleman@simiga.gov

Mr. Ludwig.

Your request for the North Georgia Live Steamers to not be required to do UT thickness readings this season per the NBIC has been approved.

This is provided that the inspector finds no areas of concern that he notes on his inspection report

concerning the internals inspections.

Also anyone who has not had a hydro (also per NBIC requirements) in the last three (3) years will do so upon inspection.

If you have any other questions feel free to contact at (404) 473-1301

Best Regards,

Ben Crawford Office of Insurance and Safety Fire Commissioner Chief Engineer/ Safety Engineering Suite 920, West Tower 2 Martin Luther King, Jr. Drive Atlanta, GA 30334 (404) 463-0726 bcrawford@sfm.ga.gov